Alpha
Consulting Engineers Pte Ltd

FEEDBACK REPORT FORM

Ref No: 101-301107(S)

To: RT From: HIA CHUEN LING

Job No./Project: — *(where applicable)*

Source of feedback: —

Scope of Feedback: *Quality System/Administrative/Contractual/Technical/Specification/Others

Section A : Problem & Cause

DRAWING NO. SE(EI)-20 REV. A.

1) 13A S.S.O. WITHIN CABINET. NOT APPROVED BY SPPG AS IT IS NOT ACCESSIBLE.

2) 13A S.S.O 50mm ABOVE CABINET DO NOT COMPLY TO CP5

Section B : Suggested Corrective Action

1) INTRODUCE 20A DP SWITCH FOR 13A S.S.O.

2) SHIFT 13A S.S.O. TO BE 150mm ABOVE WORKING SURFACE

Section C: Approved Corrective Action

Approved By : Richard Teo Date: 07/12/2007

Section D : Action


Action By: TAY KHYE TAM

Targeted Completion: 07/12/2007

Actual Completion: 07/12/2007 Verified By:

* *Delete as appropriate*

Distribution:



Drawing Title

TYPICAL INSTALLATION DETAIL OF ELECTRICAL POINT FOR COOKER HOOD, HOB & OVEN

Alpha Consulting Engineers Pte Ltd	Drawing No. SE(EI) – 20	Rev. B